

LAYOUT AT CORNER
MUST ACCOUNT FOR
FACT THAT JAMB
BLOCK CORNER
ANGLE VARIES FROM
 91° - 93°

